R69 Conductive pad Surface resistance $10^{\circ} \sim 10^{\circ} \Omega$ is launched!!

Application and Features by Vacuum Pad

| Pad type | | Characteristics | Application |
|---------------------------|----|-------------------------------|--|
| Standard type | | | Flat work (hard and thick work) |
| Deep type | | | Spherical fruit (apple, etc.) or round ball |
| Sma ll type | | | Semiconductor product |
| Bellows type | | | Vacuum packed pack |
| Multi- bellows type | | vacuum pad Vinyl, paper, etc. | and food package |
| Oval type | 1. | | Long work such as circuit borad or semiconductor product |
| Sponge type | 30 | | External wall material of building and work such as small stone and tile |

| Pad type | | Characteristics | Application |
|-------------------------|--|---|---|
| Soft type | | | Injection parts or easily |
| Soft bellows type | | vacuum pad | scratched parts. |
| Skid— proof type | | | Oily press cut parts. |
| Ultrathin type | | Breathable Plastic bag and paper pack, etc. | Copy paper, plastic film or thin work. |
| Flat type | | | Return of ultrathin type work, such as sheets, vinyl, etc. |
| Long stroke type | | Inner type external type spring | Adsorption is possible even if the height of the work is not specified. |
| Vacuum cylinder | | | A vacuum pad with a built—in cylinder and vacuum generator allows compressed air to be vacuumed and the work is adsorbed to raise the cylinder. |
| Air twee- zers | | Hole type Button type | Ideal for small work adsorption and transfer with tweezers with built—in vacuum pad and vacuum generator in pen—type body |
| Mark— free typ | | | Liquid crystal glass, painting process, semiconductor production equipment |

Conductive pad type

Standard type













VP4RSE(special)

VP6RSE

VP6RSE(LIP)

VP8RSE

VP8RSE(LIP)

VP10RSE

Bellows type

Soft bellows type













VP8BSE

VP10BSE

VP15BSE

VP6LBSE

VP6LBSE(special)

VP8LBSE

Flat type











VP10FSE

VP15FSE

VP20FSE

VP30FSE

Ultrathin type











VP8PSE

VP10PSE

VP15PSE

Conductive vacuum pad inspection method




Put it on the measuring board in 100 units.

10⁶early half ~ 10⁸latter half: Rejection

* In case of surface resistance, the resistance value may vary depending on the room temperature and humidity. We set the measurement point according to the pad size and shape, and conduct a total inspection.



Total inspection by TREK surface resistance meter



All items of vacuum pad holder are compatible

